## PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No			Dated:	
It is certified that an inspection team head	ded by CAC	don 0 /	Smo.	
(Name of Officers with designation) from ST.				
BAGDGORA, POST : BAGDOGRA, DIST	DARJEELING, I	PIN: 734421	(Name of Department/	
Office) inspected the AIR FORCE SCHO	OL BAGDGORA	, POST: B	AGDOGRA AIRPORT,	
DIST: DARJEELING, PIN- 734421 (Name	& Address of the	school) on	30 Aug 30 23 (date of	
inspection) and found that the AIR FORCE			V	
drinking water facilities for the students and	members of staff	of the institu	ution and is maintaining	
the hygienic sanitation condition in the school	ol building & the c	ampus as p	er norms prescribed by	
the Central/ State/ U.T. Govt. The above is v	alid for a period of Signature v	(f ਧਰ ਵਿ	हिंडिए एउन सिन्ह/Rishu Raj Sinna) जा. ले. / Flt Lt ा. अ. / Medical Officer ए स्कंध वायु सेना/20 Wing, Air Force	
	Name	2131	AHNIS CAR UH	
	Designation	:¢	ne sho	
	Name & Address	of the Offic	e / Department: AFS., BA	adocara
То				
AIR FORCE SCHOOL, BAGDOGRA P.O. BAGDOGRA AIRPORT, DIST-DARJEELING, (W-B) PIN-734421				